

	Type	L #	Hits	Search Text	DBs	Time Stamp	Error Count
1	BRS	L1	18	oxid\$5 same ((Ti or titanium or Al or aluminum or Ta or tantalum) adj2 mask) same (etch\$3 adj rate)	USPAT; US-PGPUB ; EPO; JPO DERWENT; IBM_TDB	2002/05/18 18:56	0
2	BRS	L8	202	expos\$3 same (Ti or titanium or Al or aluminum or Ta or tantalum) same ("prior to" or before) near5 etch\$3)	USPAT; US-PGPUB ; EPO; JPO DERWENT; IBM_TDB	2002/05/18 19:13	0
3	BRS	L15	87	438/\$.ccls. and 8	USPAT; US-PGPUB ; EPO; JPO DERWENT; IBM_TDB	2002/05/18 19:18	0
4	BRS	L22	58	15 and @pd<=19970120	USPAT; US-PGPUB ; EPO; JPO DERWENT; IBM_TDB	2002/05/18 19:18	0
5	BRS	L29	3	expos\$3 same (Ti or titanium or Al or aluminum or Ta or tantalum) same ("prior to" or before) near5 (etch\$3 adj rate))	USPAT; US-PGPUB ; EPO; JPO DERWENT; IBM_TDB	2002/05/18 19:16	0
6	BRS	L36	0	expos\$3 same (Ti or titanium or Al or aluminum or Ta or tantalum) same ("prior to" or before) near5 (etch\$3 adj rate)) same resist\$3	USPAT; US-PGPUB ; EPO; JPO DERWENT; IBM_TDB	2002/05/18 19:17	0
7	BRS	L43	133	expos\$3 same (Ti or titanium or Al or aluminum or Ta or tantalum) same (etch\$3 adj rate) same resist\$3	USPAT; US-PGPUB ; EPO; JPO DERWENT; IBM_TDB	2002/05/18 21:34	0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Er ro r C o m m e n t s	Er ro r D e f e r e n t i t i o n
8	BRS	L50	55	438/\$.ccls. and 43	USPAT; US-PGPUB ; EPO; JPO; DERWENT; IBM_TDB	2002/05/18 21:06		0
9	BRS	L57	35	50 and @pd<=19970120	USPAT; US-PGPUB ; EPO; JPO; DERWENT; IBM_TDB	2002/05/18 19:41		0
10	BRS	L64	882	(oxid\$5) same (Ti or titanium or Al or aluminum or Ta or tantalum) same (etch\$3 adj rate)	USPAT; US-PGPUB ; EPO; JPO; DERWENT; IBM_TDB	2002/05/18 20:54		0
11	BRS	L71	432	438/\$.ccls. and 64	USPAT; US-PGPUB ; EPO; JPO; DERWENT; IBM_TDB	2002/05/18 19:41		0
12	BRS	L78	202	71 and @pd<=19970120	USPAT; US-PGPUB ; EPO; JPO; DERWENT; IBM_TDB	2002/05/18 21:38		0